## **SECURITY HANDLE TUBE GHV**

## with lever valve






Lever valve for automatic stop of gas supply by releasing. Adjusting the oxygen supply with lever valve. The gas supply will be closed by loosing the lever and guarantees a high degree of safety.

| Model | A<br>Connection | L₁<br>Length<br>[mm] | L <sub>2</sub><br>Length<br>[mm] | Weight<br>[kg] | Material | Max.<br>working pressure<br>[bar] | Order-No. |
|-------|-----------------|----------------------|----------------------------------|----------------|----------|-----------------------------------|-----------|
| GHV   | 3/4"            | 258                  | 82                               | 1.03           | Brass    | Oxygen (O)<br>30.0                | 040210200 |

## Inlet connection



| Connection           |             |           |  |
|----------------------|-------------|-----------|--|
| B<br>Inlet           | A<br>Outlet | Order-No. |  |
| G 1/2 M<br>with cone | G 3/4 MG    | 100011092 |  |